

ALE Security Advisory **No. SA-N0050 Ed. 02**

AOS-W / OmniAccess Stellar - WPA2 Key Reinstallation Vulnerabilities

Summary

Common industry-wide flaws in WPA2 key management may allow an attacker to decrypt, replay, and forge some frames on a WPA2 encrypted network. These vulnerabilities may affect both AOS-W and the OmniAccess Stellar AP Operating System.

Description of Issue

See the accompanying FAQ document for more detailed information.

Reinstallation of the pairwise key in the 4-way handshake (CVE-2017-13077)
Reinstallation of the group key in the 4-way handshake (CVE-2017-13078)
Reinstallation of the integrity group key in the 4-way handshake (CVE-2017-13079)
Reinstallation of the group key in the group key handshake (CVE-2017-13080)
Reinstallation of the integrity group key in the group key handshake (CVE-2017-13081)

AOS-W and AOS-W Instant are not affected by the above vulnerabilities while acting as an authenticator (i.e. operating in standard AP mode).

AOS-W APs are affected by the above vulnerabilities while acting as a Wi-Fi supplicant in the following modes:

- Mesh

AOS-W Instant is affected by the above vulnerabilities while acting as a Wi-Fi supplicant in the following modes:

- Mesh
- Wi-Fi Uplink

Stellar APs are affected by CVE-2017-13077 and CVE-2017-13078 in a few special conditions (client initiate rekey), although these two vulnerabilities are mainly used against clients (supplicants) highlighted in media articles.

Stellar APs are affected by CVE-2017-13080.

Stellar APs are not affected by CVE-2017-13079 or CVE-2017-13081.

Severity: Medium
CVSSv3 Overall Score: 6.7
CVSS Vector: CVSS:3.0/AV:L/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N

Accepting a retransmitted FT Reassociation Request (CVE-2017-13082)

AOS-W and AOS-W Instant are affected by this vulnerability in both authenticator and supplicant modes.

Stellar APs are affected by this vulnerability when 802.11r is enabled.

Severity: Medium
CVSSv3 Overall Score: 6.7

CVSS Vector: CVSS:3.0/AV:L/AC:H/PR:N/UI:N/S:U/C:H/I:H/A:N

Reinstallation of the STK key in the PeerKey handshake (CVE-2017-13084)

Reinstallation of the Tunneled Direct-Link Setup PeerKey (CVE-2017-13086)

Reinstallation of the Group Key when processing a WNM Sleep Mode Response (CVE-2017-13087)

Reinstallation of the Integrity Group Key when processing a WNM Sleep Mode Response (CVE-2017-13088)

AOS-W products are not affected by these vulnerabilities.

Stellar APs are not affected by these vulnerabilities.

Status on Alcatel-Lucent Enterprise AOS-W and OmniAccess Stellar AP Products

List of products and releases concerned (or affected):

Product Name	Release
AOS-W	<ul style="list-style-type: none"> - AOS-W (all versions prior to 6.3.1.25) - AOS-W 6.4 prior to 6.4.4.16 - AOS-W 6.5.0.x - AOS-W 6.5.1 prior to 6.5.1.9 - AOS-W 6.5.2.x - AOS-W 6.5.3 prior to 6.5.3.3 - AOS-W 6.5.4 prior to 6.5.4.2 - AOS-W 8.x prior to 8.1.0.4 - AOS-W Instant (all versions prior to 4.2.4.9) - AOS-W Instant 4.3 prior to 4.3.1.6 - AOS-W Instant 6.5.2 and 6.5.3 prior to 6.5.3.3 - AOS-W Instant 6.5.4 prior to 6.5.4.2 <p>Note: FIPS and non-FIPS versions of software are both affected equally.</p>
OmniAccess Stellar Operating System	2.0 3.0

List of products and releases **NOT concerned** (or affected):

Product Name	Release
No other products are affected	N/A

Workarounds

Some vulnerabilities described in this advisory can be mitigated by disabling certain features:

- For AOS-W: Ensure that 802.11r is disabled by verifying that any configured SSID profile does not contain a "dot11r-profile". From the command line, "show wlan dot11r-profile" will list any 802.11r profiles that have been configured. If the reference count is 0, 802.11r is not enabled.
- For AOS-W Instant: Ensure that 802.11r is not enabled in any configured WLAN.
- For AOS-W: Disabling 802.11r on the AP infrastructure will effectively mitigate client-side 802.11r vulnerabilities. It will not, however, mitigate client-side 4-way handshake vulnerabilities.

- For AOS-W and AOS-W Instant: Mesh mode for both AOS-W and AOS-W Instant is vulnerable. Until this vulnerability is patched, mesh networks should be disabled.
- For AOS-W: Wi-Fi uplink mode for AOS-W Instant is vulnerable. Until this vulnerability is patched, the Wi-Fi uplink feature should not be used.
- For Stellar APs: CVE-2017-13077 and CVE-2017-13078 - There is no workaround.
- For Stellar APs: CVE-2017-13080 can be mitigated by disabling Broadcast Key Rotate in OV2500 (Broadcast Key Rotation is always disabled in WiFi Express mode and can't be enabled).
- For Stellar APs: CVE-2017-13082 can be mitigated by disabling 802.11r.

Resolution for Alcatel-Lucent Enterprise Affected Products

All listed vulnerabilities have been fixed in the following AOS-W patch releases, which are available for download immediately from support.esd.alcatel-lucent.com:

- 6.3.1.25
- 6.4.4.16
- 6.5.1.9
- 6.5.3.3
- 6.5.4.2
- 8.1.0.4

All listed vulnerabilities have been fixed in the following AOS-W Instant patch releases, which are available for download immediately:

- 4.2.4.9
- 4.3.1.6
- 6.5.3.3
- 6.5.4.2

Alcatel-Lucent Enterprise is currently working on updates to address these vulnerabilities on the OmniAccess Stellar AP product line. This advisory will be updated when the software updates are available.

History

Ed.01 (2017 October 16th): creation

Ed.02 (2017 October 18th): updated